

Project: Dublin CC Accessibility Audits

Job No: 23399

Use Type: Public Park

Auditor: N Williamson

Date of Audit: 13/02/2007

Capita Ref: 032

Name: Marino Park

Address: North Central

Section 1: Approach Routes & Street Furniture

REF	QUESTION	Y/N	LOCATION	RECOMMENDATION	QTY	PHOTO REF	PRIORITY	COSTS
1.1	Is the park easy to find?	No	surrounding area	<p>The park is quite difficult to find. Therefore, provide suitable signage offering directions to the main entrances. Directional signs should be suitably positioned to allow persons approaching from all directions to see them easily. For medium range location and direction signs the text height should be a minimum of 60mm. The background of the general signboard should be white and the text should be black or dark blue.</p> <p>Please refer to BS 8300 'Table 5' and 'Table 6' for further information regarding text size and colour contrast.</p>	1		1	€1,500
1.2	Is the park within convenient walking distance of: Public Highway, Public Transport, Car Parking?	Yes						

1.3	Is the surrounding approach routes level?	No		The approach route is generally level. However, there are kerbs at main crossing points that will present a hazard to persons using a wheelchair and to ambulant disabled persons. Therefore, provide suitable dropped kerbs with colour contrasting tactile paving to the following locations: either side of Brian Road, either side Croydon Gardens and either side of Croydon Park Avenue.	3	1,6,8	2	€4,500
1.4	Are the approach routes minimum 1.8m wide?	No	external perimeter	The pathway around the external of the perimeter is only approximately 800mm wide. Provide a 1.8m wide pavement around the external perimeter of the park to assist wheelchair users.	1	2	2	€50,000
1.5	Are approach route surfaces even and slip resistant?	Yes						
1.6	Do approaches to crossovers have the necessary contrasting tactile surfaces and dropped kerbs?	No		refer to 1.3				
1.7	Is the approach route to the park entrances clearly signed?	No		The signage at the entrances of the park is unsuitable. Many entrances do not have signage or the existing signage is dated and worn. Provide suitable signage at all entrances offering the opening and closing times etc. The background of the general signboard should be white and the text should be black or dark blue. Please refer to BS 8300 'Table 5' and 'Table 6' and NDA buildings for everyone for full details.	3	2,5,7	1	€1,500
1.8	Is the approach route to the park suitably lit (if park operates after dark)?	Yes						

1.9	Is the approach route to the park entrances free of hazards such as bollards, litter bins etc?	Yes
1.10	Is there a designated drop-off point close to a park entrance to allow disabled visitors arriving at the park in vehicles to be safely dropped-off? Is it well signed/marked out?	N/A

Section 3: Park Entrances

REF	QUESTION	Y/N	LOCATION	RECOMMENDATION	QTY	PHOTO REF	PRIORITY	COSTS
3.1	Is the park entrance(s) easy to find, well signed and clearly distinguishable from the façade?	No		refer to 1.7				
3.2	Is there suitable signage to the main entrance(s) of the park indicating what facilities are available to assist visitors with a disability (i.e. accessible routes, parking, toilets etc)?	No		refer to 1.7				
3.3	Is there level access to park entrances?	No		The 3No.entrances to the park are not suitable for wheelchair users. Provide level entrances to the park at each entrance that is also 800mm wide to assist wheelchair users.	3	2,6,7	1	€6,000
3.4	Are park entrances wide enough for all users (minimum 800mm)?	No		refer to 3.3				
3.5	If operated by the public, are park gate handles/controls easy to use and at a suitable height for use by visitors standing or seated?	Yes						

Section 4: Horizontal Circulation Routes

REF	QUESTION	Y/N	LOCATION	RECOMMENDATION	QTY	PHOTO REF	PRIORITY	COSTS
4.1	Are circulation routes within the park at least 1800mm wide (or have regular 1800mm wide passing zones)?	No		There are currently no designated pathways within the park. Provide suitable pathways in the park linking the entrances with the circulation space and the football pavilion.	1		1	€20,000
4.2	Are surfaces even and slip resistant?	No		refer to 4.2				
4.3	Is park signage suitably positioned, sized and with necessary colour/tonal contrast between letters and background? Is there alternative pictorial signage indicating key park features/warnings etc?	N/A						
4.4	Is adequate seating with armrests provided in larger parks?	N/A						
4.5	Does the park allow general movement to all areas; accessible paths, accessible gates, segregation of pedestrians from vehicles?	N/A						
4.6	Are circulation routes kept free of debris, foliage, overgrown plants/shrubs etc?	No		Ensure that all pathways are kept clear of debris/mud/overgrown grass etc to assist persons with visual and mobility impairments.	1		4	€0

