

Project: Dublin CC Accessibility Audits

Job No: 23399



Use Type: Public Park

Auditor: N Williamson

Date of Audit: 13/02/2007

Capita Ref: 020

Name: Collagreena Close

Address: North Central

Section 1: Approach Routes & Street Furniture

REF	QUESTION	Y/N	LOCATION	RECOMMENDATION	QTY	PHOTO REF	PRIORITY	COSTS
1.1	Is the park easy to find?	No		The park is quite difficult to find. However, it would appear that the park is only used by local who will have knowledge of its locations. No recommendation is being made to provide directional signage in this instance.				€0
1.2	Is the park within convenient walking distance of: Public Highway, Public Transport, Car Parking?	Yes						
1.3	Is the surrounding approach routes level?	Yes						
1.4	Are the approach routes minimum 1.8m wide?	Yes						
1.5	Are approach route surfaces even and slip resistant?	Yes						
1.6	Do approaches to crossovers have the necessary contrasting tactile surfaces and dropped kerbs?	N/A						

1.7	Is the approach route to the park entrances clearly signed?	No		Provide suitable signage at all entrances offering the opening and closing times etc. The background of the general signboard should be white and the text should be black or dark blue. Please refer to BS 8300 'Table 5' and 'Table 6' and NDA buildings for everyone for full details.	1	1	1	€500
1.8	Is the approach route to the park suitably lit (if park operates after dark)?	Yes						
1.9	Is the approach route to the park entrances free of hazards such as bollards, litter bins etc?	No	Coolgreena Close	There are hazardous bollards on the approach route to the park. This may present a problem for persons with a visual impairment. Reposition the obstruction out with the access approach. If this is not feasible ensure that any bollards and litterbins etc. contrast in colour and luminance with the surroundings.	1	3	2	€500
1.10	Is there a designated drop-off point close to a park entrance to allow disabled visitors arriving at the park in vehicles to be safely dropped-off? Is it well signed/marked out?	N/A						

Section 3: Park Entrances

REF	QUESTION	Y/N	LOCATION	RECOMMENDATION	QTY	PHOTO REF	PRIORITY	COSTS
3.1	Is the park entrance(s) easy to find, well signed and clearly distinguishable from the façade?	No		refer to 1.7				

3.2	Is there suitable signage to the main entrance(s) of the park indicating what facilities are available to assist visitors with a disability (i.e. accessible routes, parking, toilets etc)?	No	refer to 1.7
3.3	Is there level access to park entrances?	Yes	
3.4	Are park entrances wide enough for all users (minimum 800mm)?	Yes	
3.5	If operated by the public, are park gate handles/controls easy to use and at a suitable height for use by visitors standing or seated?	N/A	

Section 4: Horizontal Circulation Routes

REF	QUESTION	Y/N	LOCATION	RECOMMENDATION	QTY	PHOTO REF	PRIORITY	COSTS
4.1	Are circulation routes within the park at least 1800mm wide (or have regular 1800mm wide passing zones)?	Yes						
4.2	Are surfaces even and slip resistant?	Yes						
4.3	Is park signage suitably positioned, sized and with necessary colour/tonal contrast between letters and background? Is there alternative pictorial signage indicating key park features/warnings etc?	N/A						
4.4	Is adequate seating with armrests provided in larger parks?	N/A						

4.5	Does the park allow general movement to all areas; accessible paths, accessible gates, segregation of pedestrians from vehicles?	Yes		1	4	€0
4.6	Are circulation routes kept free of debris, foliage, overgrown plants/shrubs etc?	No	Ensure that all pathways are kept clear of debris/mud/overgrown grass etc to assist persons with visual and mobility impairments.	1	4	€0

