

		2020 (Inside Bathing Season)																												2020/21 (Outside of Bathing Season)							
Designated Bathing Areas	DATE OF SAMPLE	02/06	08/06	15/06	19/06*	22/06	28/06	01/07	03/07*	06/07	10/07*	15/07	20/07	26/07	29/07	04/08	09/08	10/08	17/08	*19/08	24/08	27/08*	31/08	03/09*	06/09	14/09	13/10	28/10	11/11	17/11							
	DOLLYMOUNT																																				
	SANDYMOUNT																																				
Non-Designated Bathing Areas	MERRION																																				
	SHELLEY BANKS																																				
	HALF MOON																																				
	NORTH BULL WALL CAUSEWAY																																				

	Indicates excellent water quality – Samples should not exceed 250 MPN E. Coli and 100 CFU Intestinal Enterococci per 100 ml.
	Indicates good water quality – Samples should not exceed 500 MPN E. Coli and 200 CFU Intestinal Enterococci per 100 ml.
	Indicates sufficient water quality - samples should not exceed 1,000 MPN E. coli and 250 CFU Intestinal Enterococci per 100 ml
	Indicates poor water quality - samples exceed 1,000 MPN E. coli and 250 CFU Intestinal Enterococci per 100 ml
Date*	Additional Investigative Sampling carried out

MPN = Most Probable Number
CFU = Colony Forming Unit