

Project: Dublin CC Accessibility Audits

Job No: 23399



Use Type: Public Park

Auditor: G Speirs

Date of Audit: 21/03/2007

Capita Ref: 089

Name: Clonmacnoise / Bangor Circle

Address: South Central

Section 1: Approach Routes & Street Furniture

REF	QUESTION	Y/N	LOCATION	RECOMMENDATION	QTY	PHOTO REF	PRIORITY	COSTS
1.1	Is the park easy to find?	No		Refer to item 1.7.				€0
1.2	Is the park within convenient walking distance of: Public Highway, Public Transport, Car Parking?	Yes						
1.3	Is the surrounding approach routes level?	No	Approach Routes	There is limited level access to and from the site. Recommend the installation of dropped kerbs on the main approach routes to entrance areas. Budgetary cost included for 8 No.	8	1	2	€6,000
1.4	Are the approach routes minimum 1.8m wide?	Yes						
1.5	Are approach route surfaces even and slip resistant?	Yes						
1.6	Do approaches to crossovers have the necessary contrasting tactile surfaces and dropped kerbs?	No		There is limited physical assistance on route to the park. Recommend that crossover points be incorporated with tactile blister paving to either side. This need only be incorporated on the main approach routes. A budgetary cost is included.	2	1,3	2	€2,000

1.7	Is the approach route to the park entrances clearly signed?	No		The park is not well signed on approach. Recommend that signage be provided on all major approach routes. A budgetary cost is included.	1,3	1	€200
1.8	Is the approach route to the park suitably lit (if park operates after dark)?	No	Within Confines of Park	Park opening times are not known and the existing levels of lighting would not be sufficient to accommodate use at times when natural light has faded. Recommend installation of lighting / additional lighting to highlight location of main access routes / points of attraction. A budgetary cost is included. Management to determine the level of use after dark prior to implementation of additional lighting.	1	2	€5,000
1.9	Is the approach route to the park entrances free of hazards such as bollards, litter bins etc?	No		The entrance to the park is obstructed by bollards - photo 3. Recommend bollards have colour or tonal contrast applied to highlight their location and assist those with a visual impairment.	3	1	€50
1.10	Is there a designated drop-off point close to a park entrance to allow disabled visitors arriving at the park in vehicles to be safely dropped-off? Is it well signed/marked out?	N/A					

Section 3: Park Entrances

REF	QUESTION	Y/N	LOCATION	RECOMMENDATION	QTY	PHOTO REF	PRIORITY	COSTS
3.1	Is the park entrance(s) easy to find, well signed and clearly distinguishable from the façade?	No		Refer to item 3.2.				€0

3.2	Is there suitable signage to the main entrance(s) of the park indicating what facilities are available to assist visitors with a disability (i.e. accessible routes, parking, toilets etc)?	No	The park is not well signed at entrance areas. Recommend that signage be provided at all entrances to indicate its name and purpose etc (if applicable). A budgetary cost is included.	1,3	1	€200
3.3	Is there level access to park entrances?	No	Is is not considered reasonable to alter the natural topography of th site as access can still be gained into most areas of the park.	1,2,3		€0
3.4	Are park entrances wide enough for all users (minimum 800mm)?	Yes				
3.5	If operated by the public, are park gate handles/controls easy to use and at a suitable height for use by visitors standing or seated?	N/A				

Section 4: Horizontal Circulation Routes

REF	QUESTION	Y/N	LOCATION	RECOMMENDATION	QTY	PHOTO REF	PRIORITY	COSTS
4.1	Are circulation routes within the park at least 1800mm wide (or have regular 1800mm wide passing zones)?	Yes						
4.2	Are surfaces even and slip resistant?	Yes						
4.3	Is park signage suitably positioned, sized and with necessary colour/tonal contrast between letters and background? Is there alternative pictorial signage indicating key park features/warnings etc?	N/A						

4.4	Is adequate seating with armrests provided in larger parks?	No	There is insufficient seating within the park. Recommend that seating be provided with arm rests and back support. A budgetary cost is given for approximately 2 No. benches / seating.	2 No.	2	€800
4.5	Does the park allow general movement to all areas; accessible paths, accessible gates, segregation of pedestrians from vehicles?	No	Refer to item 3.3.			€0
4.6	Are circulation routes kept free of debris, foliage, overgrown plants/shrubs etc?	Yes				

